



GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:					
Company	Vicky Miller				
OGM	Steve Demczak				

Inspection Report

Permit Number:	C0070034			
Inspection Type:	COMPLETE			
Inspection Date:	Thursday, May 19, 2011			
Start Date/Time:	5/19/2011 10:00:00 AM			
End Date/Time:	5/19/2011 12:00:00 PM			
Last Inspection:	Wednesday, February 16, 2011			

Inspector: Steve Demczak.
Weather: Cold, Lower 50,s

InspectionID Report Number: 2761

Accepted by: jhelfric 6/1/2011

Permitee: BANNING

Operator:

Site: BANNING SIDING LOADOUT

Address: ,

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

36.42	Total Permitted			
21.60	Total Disturbed			
	Phase I			
	Phase II			
	Phase III			

Mineral Ownership

✓ Federal

State

Fee Other

County

Underground
Surface
Loadout
Processing
Reprocessing

Types of Operations

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Condition: Canyon Fuel Company has just one permit condition for the Banning Loadout; to submit water quality data in an electronic format through the Electronic Data Input web site.

Inspector's Signature:

Date

Tuesday, MayonR1

)

OIL, GAS & MINING

Permit Number: C0070034 Inspection Type: COMPLETE

Inspection Date: Thursday, May 19, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		~	
2.	Signs and Markers	~		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		~	
4.c	Hydrologic Balance: Other Sediment Control Measures	~			
4.d	Hydrologic Balance: Water Monitoring	✓			
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	~		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation		✓		
14.	Subsidence Control		✓		
15.	Cessation of Operations	✓		~	
16.8	a Roads: Construction, Maintenance, Surfacing	V			
16.t	Roads: Drainage Controls	✓		~	
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations	✓		~	
19.	AVS Check	₹			
20.	Air Quality Permit	✓		✓	
21.	Bonding and Insurance	✓		✓	
22.	Other				

Permit Number: C0070034 Inspection Type: COMPLETE

Inspection Date: Thursday, May 19, 2011

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

There are no permitting actions with the Division. The permit will expire on 11/24/2013. The SPCC Plan was reviewed on December 3, 2007.

2. Signs and Markers

The identification signs is at the gate to the property.

3. Topsoil

No topsoil piles. This is a pre-law disturbance.

4.a Hydrologic Balance: Diversions

Diversions and culverts were opened.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment pond and did not see any hazardous conditions. The permittee inspected the sediment pond on April 21, 2011. No hazardous conditions were reported. The pond contain little to no water.

4.e Hydrologic Balance: Effluent Limitations

No discharge for the first quarter of 2011.

8. Noncoal Waste

The disturb area was clear of non-coal waste materials.

15. Cessation of Operations

The site has some storage for mine equipment. Buildings, conveyors, rail loadout equipment has been removed.

16.b Roads: Drainage Controls

Diversions are functioning.

18. Support Facilities, Utility Installations

No new construction at this site.

20. Air Quality Permit

Air Quality Permit number is 533-6108.

21. Bonding and Insurance

The insurance policy will expire on July 31, 2011. The bonding amount is \$350,000.